
### SLAM -- Fall 2013 Status Update







## **Construction Sequencing**



1. Construction of Phase Za - Secure Vault



3. Demolition




2. Safe Transfer of Museum Objects




4. Construction of Phase 2b.

## **Construction Underway - Access**



## Risk Management -- Tidal Influence





## Risk Management -- Tidal Influence





## Quality – Waterproofing Mock-up




# Quality – Exterior Wall Testing



## Quality – Concrete







### Safety

#### Pedestrian Safety – the problem

Roughly 25 reported incidents to date at Egan Drive and Whittier Street

#### Follow traffic rules – best practices

- ✓ Be aware of your own safety in the crosswalks.
- ✓ Make eye contact with vehicle driver
- ✓ Wear reflective coats/jackets
- ✓ Use light baton (see PCL project office)

#### Other measures underway:

- 1. Yield to Pedestrians sign Completion fall 2013
- 2. Egan Drive (Main street to the Bridge) Pedestrian and Bicycle Safety Project Completion 2016
- 3. Evaluation of leading pedestrian interval, new crosswalk at west side of Whittier, flashing yellow turn signal.





#### **Construction Timeline**

